

**Property Information**

**Property Names**

<b>Name Explanation</b>	<b>Name</b>
Function/Location	House, 20 River Road

**Property Evaluation Status**

Not Evaluated

**Property Addresses**

Current - 20 River Road

**County/Independent City(s):** Richmond (Ind. City)

**Incorporated Town(s):** *No Data*

**Zip Code(s):** 23226

**Magisterial District(s):** *No Data*

**Tax Parcel(s):** *No Data*

**USGS Quad(s):** BON AIR

**Additional Property Information**

**Architecture Setting:** Suburban

**Acreage:** 2

**Site Description:**

2007: Located up on a bluff facing River Road to the east and the Country Club of Virginia golf course to the west. House is situated in a manicured lawn surrounded by mature hardwoods.

**Surveyor Assessment:**

*No Data*

**Surveyor Recommendation:** *No Data*

**Ownership**

<b>Ownership Category</b>	<b>Ownership Entity</b>
Private	<i>No Data</i>

**Primary Resource Information**

**Resource Category:** Domestic

**Resource Type:** Single Dwelling

**NR Resource Type:** Building

**Historic District Status:** *No Data*

**Date of Construction:**

**Date Source:** *No Data*

**Historic Time Period:** *No Data*

**Historic Context(s):** Domestic

**Other ID Number:** *No Data*

**Architectural Style:** No Discernable Style

**Form:** *No Data*

**Number of Stories:** 2.0

**Condition:** Excellent

**Threats to Resource:** None Known

**Architectural Description:**

2007: Frame; two story; 4 bays; hipped roof with standing seam metal; one-story porch with shed roof and square posts; side screened-in one story porch with shed roof; central interior brick chimney; sash, double-hung windows with 6 over 6 lights. Eear frame addition; two stories; hipped standing seam metal roof; central interior chimney; sash double-hung windows with 1 over 1 lights.

**Exterior Components**

Component	Component Type	Material	Material Treatment
Windows	Sash, Double-Hung	Wood	6/6

Porch	1-story, 3-bay	Wood	Enclosed
Chimneys	Interior	Brick	<i>No Data</i>
Roof	Hipped	Metal	Standing Seam
Windows	Sash, Double-Hung	Wood	1/1
Porch	1-story, 4-bay	Wood	Columns, Square
Foundation	Slab	Brick	<i>No Data</i>
Structural System and Exterior Treatment	Frame	Wood	<i>No Data</i>

**Secondary Resource Information**

**Historic District Information**

**Historic District Name:** *No Data*  
**Local Historic District Name:** *No Data*  
**Historic District Significance:** *No Data*

**CRM Events**

**Event Type: Other**

**Project Review File Number:** *No Data*  
**Investigator:** *No Data*  
**Organization/Company:** Unknown (DSS)  
**Photographic Media:** *No Data*  
**Survey Date:** 1/30/2007  
**Dhr Library Report Number:** *No Data*  
**Project Staff/Notes:**  
*No Data*

**Bibliographic Information**

**Bibliography:**  
*No Data*  
**Property Notes:**  
*No Data*




**Legend**

- Architecture Resources
- Architecture Labels
- Individual Historic District Properties
- Archaeological Resources
- Archaeology Labels
- DHR Easements
- USGS GIS Place names
- County Boundaries



Feet



**Title: Architecture Labels**

**Date: 5/31/2019**

*DISCLAIMER: Records of the Virginia Department of Historic Resources (DHR) have been gathered over many years from a variety of sources and the representation depicted is a cumulative view of field observations over time and may not reflect current ground conditions. The map is for general information purposes and is not intended for engineering, legal or other site-specific uses. Map may contain errors and is provided "as-is". More information is available in the DHR Archives located at DHR's Richmond office.*

*Notice if AE sites: Locations of archaeological sites may be sensitive the National Historic Preservation Act (NHPA), and the Archaeological Resources Protection Act (ARPA) and Code of Virginia §2.2-3705.7 (10). Release of precise locations may threaten archaeological sites and historic resources.*