

Staff Report City of Richmond, Virginia



Commission of Architectural Review

1.COA-137318-2023	Final Review	Meeting Date: 10/24/2023
Applicant/Petitioner	Robert Ries	
Project Description	Alter an existing front façade door opening.	
Project Location	108 403 403 401 921 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
Address: 411 Brook Road	400 410 410 455 455 455 455 455 455 455 455 455 45	200
Historic District: Jackson Ward	(a) (a) (b) (a) (a) (a) (a) (a) (a) (a) (a) (a) (a	
High-Level Details:	327 A197 A197 A197 A197 A197 A197 A197 A19	05 100 100 100 100 100 100 100 100 100 1
Applicant requests approval to alter the primary entrance of a mixed-use, Italianate building ca. 1880.	115 313 23 210 213 418 319 319 319 319 310 308 342 310 308 342	401 110 110 110 110 110 110 110 110 110
 The first-floor storefront has been previously altered and the front door and door jamb does not appear to be original to the building. 	500 222 220 221 200 200 200 200 200 200 2	110 m 100 m
The front door will be raised eight to ten inches, the vestibule floor being raised by installing wood or stone.	22 22 21 215 0 0.01 0.02 0.04 0.06 /115 /1208 Miles	19) 191 101 101 101 101 101 101 101 101 101
Staff Recommendation	Approval, with Conditions	
Staff Contact	Alex Dandridge, (804) 646-6569, alex.dandrdige@rva.gov	
Previous Reviews	The Commission reviewed and approved the reopening of a rear window on this property in May 2023.	
	Staff administratively approved the door and transom window in Nov location and dimensions were not	ember 2022. Door opening
Staff Recommendations	Staff Recommends:	
	 If a new front door is insta administrative approval gu replacement and be submi review and approval. Final step material (wood, submitted for administration) 	uidelines for front door itted for administrative stone, concrete) be

Staff Analysis

Guideline Reference	Reference Text	Analysis
Building Elements, Porches, Entrances & Doors, Porch and Entrance Repair	significantly altered and does not feature original overall historic character. 11. A primary entrance should not be altered to give an appearance that was not originally intended 14. Do not remove original doors and door surrounds. 15. Brook Road. The storefront at 415 Brook Road does not feature original configuration. While S was not able to find documentation for the storefront alterations, it appears the storefront windows were reconstructed to match the neighboring buildings. Based on historic photographs, the original storefront likely matched building at 415 Brook Road. The storefront at 415 Brook Road does not ap to be as significantly altered, and does not feet a vestibule. Staff believes the vestibule/recess entrance at 411 Brook Road is not based-off or original configuration. Photographic	storefront alterations, it appears the storefront windows were reconstructed to match the neighboring buildings. Based on historic photographs, the original storefront likely matched that of the attached building at
		documentation of 411 & 415 Brook Road supports
		The applicant does not plan to alter the existing storefront configuration.
		An 8-10" wood or stone step will be added to the floor of the recessed entrance, raising the door. Other properties on the subject block feature either a wooden or concrete step within their primary entrance.
		Staff does not believe that the installation of a wooden or concrete step would significantly alter the visual appearance of the building, and will not impact the integrity of the building. Staff recommends approval of the installation of a wooden or stone step within the recessed primary entrance.
		While not specifically mentioned in the application, Staff recommends that if a new front door is installed, it meet the administrative approval guidelines for front door replacement and be submitted for administrative review and approval.
		Staff recommends that the final step material (wood, stone, concrete) be submitted for administrative review and approval.

Figures

Figure 1. 411 Brook Road, approximately 1955, City of Richmond Assessors Office. Some original components/materials of the storefront are present.



Figure 2. 411 Brook Road, 1997. Storefront infilled with brick. Poor condition. Original materials and configuration have been removed/altered.



Figure 3. 411 Brook Road, existing conditions 2023. Google Street view 2023, accessed October 20, 2023.



Figure 3. Primary entrances along Brook Road that feature a wooden, stone, or concrete step.

