

APPLICATION FOR CERTIFICATE OF APPROPRIATENESS ECE VED

PROPERTY (location of work) 100 Fast Leigh Street JAN 2 5 2018	Date/time rec'd: 18
Address 100 East Leigh Street	riec a by: The the
Historic district Jackson Ward	Application #: (09-039601-30)8 Hearing date: 2/27/18
APPLICANT INFORMATION	
_{Name} Augustus Johnson IV	Phone 804.212.4028
Company	Email gjohnson195@gmail.com
Mailing Address 100 East Leigh Street	Applicant Type: ■ Owner
Richmond, VA 23219	☐ Lessee ☐ Architect ☐ Contractor Other (please specify):
OWNER INFORMATION (if different from above)	
Name	Company
Mailing Address	Phone
	<u>Email</u>
PROJECT INFORMATION	<u></u>
Review Type: Conceptual Review Final Review	
Project Type: ■ Alteration □ Demolition	☐ New Construction (Conceptual Review Required)
Project Description: (attach additional sheets if needed)	
Replacement of eleven (11) inoperable/broken window	s on main residence, with windows of
similar color, style, design, and layout. No visual chang	es to exterior of building.
ACKNOWLEDGEMENT OF RESPONSIBILITY	· · ·
Compliance: If granted, you agree to comply with all conditions of the Co and may require a new application and CAR approval. Failure to comply action. The COA is valid for one (1) year and may be extended for an add	with the COA may result in project delays or legal
Requirements: A complete application includes all applicable information and accurate description of existing and proposed conditions. Preliminar necessary to process the application. Owner contact information and significant process are considered.	y review meeting or site visit with staff may be
Zoning Requirements: Prior to CAR review, it is the responsibility of the	
required and application materials should be prepared in compliance wi	th zoning.
Signature of Owner	Date 1/12/18

Window Replacement - Detailed Description - 100 East Leigh Street

Eleven (11) inoperable/broken windows were replaced on the front and side of the main residence. This work was performed on January 10th, 2018 by Skyline Windows. The seven (7) windows on the front of the residence that were replaced, were replacement type windows believed to have been installed in the mid-1990s, all windows were painted and nailed shut. The remaining four (4) windows on the side of the residence were in very poor condition and had been painted, caulked, and nailed shut by previous owners. All of these windows noticeably leaked air especially in winter conditions.

All new windows are of similar style, design, color, and layout to windows that they replaced. All windows were custom built to fit the exact dimensions of the windows that they replaced; no new openings were cut into the home, nor were the existing openings altered. Visually the exterior of the property remains as it was before any work was performed. Additionally, of the thirty (30) windows attached to the main residence the remaining nineteen (19) had previously been replaced with similar style double hung vinyl windows. All thirty (30) windows attached to main residence are now double hung, double paned, vinyl windows.

We apologize for not submitting the application for a Certificate of Appropriateness ahead of performing this work. This was an unintentional error due to a misunderstanding of the requirements for submission of this application.



WINDOW ASSESSMENT FORM

Property Address: 100 E. LEIGH 5+

	Window Information (eral C	onditio	on	Window Assessment							3.53
Window #	Style	Width and Height	Material	Paint condition?	Square?	Operable?	Missing or broken panes?	Sill and Head	Jambs	Rails	Stiles	Muntins	Panes and Glazing Putty	Total Value	Proposed treatment
1	Double- hung 2/2	36" x 78"	Wood	Poor	Yes	No	Yes	2	1	2	1	1	3	10	Replace and reglaze broken panes, waterproof and repaint wood.
l	Double Hung	25.5" SÅ	Wnd	οĸ	Yes	No	N۰	1	2	3	4	1	1	9	Replace
2	Double Hung	25.5 54	Wood	ok	N.	No	70	1	2	3				9	Replace
3	Double	25.5 94	Mood	OK	Yes	No	No	1	2	3	١	1		9	Peplace
4	Duble Hung	25.5	Wood	OK	Yos	N.	No	1	2	3				9	Replace
5	Duble		Wood	OK	Yes	No	No	4	2	3	1	1	1	9	Replace



WINDOW ASSESSMENT FORM

Property Address: 100 E. LEIGI+ St


	Window Information General			eral Co	onditio	nc	Window Assessment								
Window#	Style	Width and Height	Material	Paint condition?	Square?	Operable?	Missing or broken panes?	Sill and Head	Jambs	Rails	Stiles	Muntins	Panes and Glazing Putty	Total Value	Proposed treatment
1	Double- hung 2/2	36" x 78"	Wood	Poor	Yes	No	Yes	2	1	2	1	1	3	10	Replace and reglaze broken panes, waterproof and repaint wood.
6	Duble Hung	25.5 N 84.25	Wad	oK	Ves	No	No	1	2	3	1	1	1	9	REPlace
7	Double Hung	200	muq	oK	Yes	No	No	H	2	3	N.			9	Replace
8	Duble Itung		Wnd	οK	No	راه	No	1	3	3	3	2	1	13	Replace
9	Double Hung	74.8 17	Word	OK	No	No	Nb		3	3	3	2		13	Replace
10	Double	0.1	Word	οK	No	No	No	-	3	3	3	3	1	14	Replace





WINDOW ASSESSMENT FORM

Property Address: 160 E. LEIGH ST

Window Ir	formati	on	Gen	eral C	onditi	on		Window Assessment						
Style	Width and Height	Material	Paint condition?	Square?	Operable?	Missing or broken panes?	Sill and Head	lambs	Rails	Stiles	Muntins	Panes and Glazing Putty	Total Value	Proposed treatment
Double- hung 2/2	36" x 78"	Wood	Poor	Yes	No	Yes	2	1	2	1	1	3	10	Replace and reglaze broken panes, waterproof and repaint wood.
Daible Hung	24 70	Mog	oK	16	Ϋ́ο	No	1	3	3	3	3	1	14	REplace
										Au				
				111										
	Double-hung 2/2	Double- 36" hung x 2/2 78"	Double- 36" hung x Wood 2/2 78"	Double-hung X Wood Poor 7/2 78" Wood Poor 7/2 78"	Square? Square?	Style Material Material Material Material Material Material Mood Poor Yes No Square?	Style Material Material	Pand Head Sill and Head	Parple At Height and Height A Material Material Material Material Material Material Material A Moorable? Sill and Head Sill and Head Sill and Head Sill and Head	Paint Condition? Naterial Material Material Material Massing or A-A-Baint Condition? Sill and Head Square? Apple A-A-Baint Condition? Salare? Square? Apple A-A-Baint Condition? Salare? Square? Salare? Salare? Salare? Salare? Salare? Square? Salare? Sal	Paint Condition Styles Siles Siles Styles Style	Double-hung X Wood Poor Yes No Yes 2 1 2 1 1 Whole Stiles A Stiles or Rails A Stiles A Stile	Panes and Glazing Purty (Glazing Purty)	Panes and dead of classing purty and the sand of classing purt









Dealer Quotation - Quote 112819

10250 Philipp Pkwy Streetsboro, OH 44241 www.soft-lite.com

JOHNSONG110817

Phone: (330) 528 3400 Fax: (330) 528 3501

QUOTE EXPIRES 30 DAYS FROM REQUESTED

Bid For

SKYLINE WINDOWS OF RICHMOND

9001 BROOK RD RICHMOND, VA 23227 Business: (804) 270-4008 Fax: 804 249 9500

713041

1/12/2018

Shipping Address

9001 BROOK RD RICHMOND, VA 23227

		」∟`	Spore tamile: Doulisoned Line 1.	
				· · · · · · · · · · · · · · · · · · ·
Customer Number	PO		Required Date	Ouoted By

Line	Qty	Description
10-1	3	BAR Double Hung Double Hung 25.5 x 54

22 2

RD - 25 78 NFRC Values

U-FACTOR	SHGC
0.29	0.3
VT	CR
0.55	60

Viewed from Inside Base Color = Soft-Lite White Half Screen Sill Expander = Y Lock Type = Standard Lock Color = Soft-Lite White Double Locks = Y Glass Package = Lowe+ & Argon Lowe = Climaguard 7036 Argon Gas Stainless Intercept Single Strength Wrap = G

Comment/Room: None Assigned

гауј

Bid Dated:

Customer Number	PO	Required Date	Quoted By
713041	JOHNSONG110817	1/12/2018	гауј

Line	Qty	Description
20-1	4	BAR Double Hung Double Hung 25.5 x 84.25

Viewed from Inside
Base Color = Soft-Lite White
Half Screen
Sill Expander = Y
Lock Type = Standard
Lock Color = Soft-Lite White
Double Locks = Y
Glass Package = Lowe+ & Argon
Clear = Yes
Lowe = Climaguard 7036
Argon Gas

Stainless Intercept


Single Strength Wrap = G Comment/Room: None Assigned



NFRC Values

U-FACTOR	SHGC
0.29	0.3
VT	CR
0.55	60

Line	Qty	Description
30-1	1	BAR Double Hung Double Hung 41.25 x 70



NFRC Values

U-FACTOR	SHGC
0.29	0.27
VT	CR
0.49	60

Viewed from Inside
Base Color = Soft-Lite White
Half Screen
Sill Expander = Y
Lock Type = Standard
Lock Color = Soft-Lite White
Reinforced Sash = Y
Double Locks = Y
Glass Package = Lowe+ & Argon
Clear = Yes
Lowe = Climaguard 7036
Argon Gas
Stainless Intercept
Single Strength
Contour
Colonial
Grid Color = Soft-Lite White
3W2H
Wrap = G


Comment/Room: None Assigned

Customer Number	PO	Required Date	Quoted By
713041	JOHNSONG110817	1/12/2018	rayj

Line	Qty	Description
40-1	1	BAR Double Hung Double Hung 41.25 x 69.75

Comment/Room:

None Assigned




NFRC Values

U-FACTOR	SHGC
0.29	0.27
VT	CR
0.49	60

Viewed from Inside Base Color = Soft-Lite White Half Screen Sill Expander = Y Lock Type = Standard Lock Color = Soft-Lite White Reinforced Sash = Y Double Locks = Y Glass Package = Lowe+ & Argon Clear = Yes Lowe = Climaguard 7036 Argon Gas Stainless Intercept Single Strength Contour Colonial Grid Color = Soft-Lite White 3W2H Wrap = G

Line	Qty	Description
50-1	2	BAR Double Hung Double Hung 34 x 70



NFRC Values

U-FACTOR	SHGC	
0.29	0.27	
VT	CR	
0.49	60	

Viewed from Inside Base Color = Soft-Lite White Half Screen Sill Expander = YLock Type = Standard Lock Color = Soft-Lite White Reinforced Sash = Y Double Locks = Y Glass Package = Lowe+ & Argon Clear = Yes Lowe = Climaguard 7036 Argon Gas Stainless Intercept Single Strength Contour Colonial Grid Color = Soft-Lite White 2W1H Wrap = G

Comment/Room: None Assigned

Skyline Windows of Richmond 7051 b Brook Road Richmond, VA 23227

Tel (804) 270-4008 Fax (804) 249-9500



MAKING INFORMED DECISIONS

MAKING SMART DECISIONS

10/18/2017

Gus Johnson 100 East Leigh Street Richmond VA 23219

We hereby submit specifications and estimates for:

Ouantity Product Soft-Lite Barrington Double Hung Replacement Windows, White Interior, White Exterior, Welded Sashes and Frame All Material is Non-Recycled(Virgin Vinyl) Interlock System at Meeting Rail Double Locks On All Units Over 24" Width

U Value

The lower the U-factor (value) the more energy efficient the windows will be. The U-factor calculates the total window's energy

efficiency (glass and frame). A difference of .01 in the U-factor changes the energy efficiency of the product by almost 4%. The U-factor

is the most important energy number when choosing a window. Consumers can go to www.nfrc.org to view any windows U-factor.

U-value .29

Air Leakage

The lower the air infiltration number, or Air Leakage(AL), the better. The AL number tells you how tight the window seals around the edges.

Solar Heat Gain Coefficient

Solar Heat Gain has to do with how much direct sunlight actually passes through the glass. In Northern states a higher SHGC number is

advantageous. In the Southern states a lower SHGC number is beneficial. Also if you have some windows that receive direct summer sun

(usually from windows facing South or/and West you should consider purchasing some windows with a lower SHGC. Be careful – a lower

SHGC could stop the beneficial solar heat during the colder months. Consumers can go to www.efficientwindows.com to view helpful criteria


in selecting the proper Solar Heat Gain number. For Virginia the best SHGC is between .25 - .35

SHGC

.26

Energy Saving Glass with

Hi Performance Soft-Coat Double Pane, ClimaGuard Low Emissisity Glass Argon filled insulated glass units Double pane high energy efficient glass



ClimaGuard™ heat reflective coating

With half screen

With Internal Flat Grids in 4 Windows on windows on the side of the house in grid pattern of customer's choice

Remove and replace any rotten wood Remove existing window & install and plumb new windows Seal interior and exterior with premium grade sealants

Haul away all old windows and debris. Inspect and clean new windows.

Tax and Installation included

WE PROPOSE to furnish materials and labor, complete and in accordance with the above specifications, for the sum of \$5,000.00. This proposal may be withdrawn by us if not accepted within 30 days.

Cash or Check All Offers/Discounts Applied

Authorized Signature

Jared Ray

Thank you for considering Skyline Windows of Richmond. We are confident that we can provide the best product, workmanship and price for the work described above.

If you have any questions, please give us a call. We look forward to hearing from you soon.

Serving Central Virginia since 1987 Quality and Service for Everyone