

COMMISSION OF ARCHITECTURAL REVIEW APPLICATION/CERTIFICATE OF APPROPRIATENESS

PROPERTY (Location of Work)			
Address 407 North Allew 1	AVC.	PNUE, UNITE Richmond 23222	0
Historic District MONUMONT	W	Will "	
PROPOSED ACTION			
Alteration (including paint colors)		Rehabilitation	
☐ Addition		New Construction (Conceptual Review required)	
		□ Conceptual Review □ Final Review	
OWNER DOWNER M + CAROLYN		APPLICANT (if other than owner)	
Name + MCCORMACK		Name	
Company		Company	
Mailing Address 485 OAK HIII ROAL	<u></u>	Mailing Address	
LANCASIER, VA 22305			
Phone 804 514 8130		Phone	
Email Inco RMAK C. ROCKET MA	1.4	Email	
Signature Caracign & mcCorna.	A	Signature	
Date Dam DOR 1, 2016		Date	
ACKNOWLEDGEMENT OF RESPONSIBILITY			
Requirements: A complete application includes all applicable information requested on checklists to provide a complete and accurate description of existing and proposed conditions. Preliminary review meeting or site visit with staff may be necessary to process the application. Owner contact information and signature is required. Late or incomplete applications will not be considered.			
Zoning Requirements: Prior to CAR review, it approval is required and application materials shaped and application materials.		e responsibility of the applicant to determine if zoning be prepared in compliance with zoning.	
require staff review and may require a new appl	icatio	Ill conditions of the COA. Revisions to approved work on and CAR approval. Failure to comply with the COA A is valid for one (1) year and may be extended for an	
(Space below for staff use only) ECE VED			
Application received: 0EC 12 201	6		
Date/Time	0	Complete	

Addendum to Application/Certificate of Appropriateness dated December 7, 2016

Subject: 407 North Allen Avenue, Richmond, VA 23220 - Unit 1 (first floor)

My wife and I own the captioned property. Unit 1 is the first floor of a three unit condominium. Unit 2 and Unit 3 are the second and third floor, respectively, of the building.

We want to replace the three window that form the bay windows of Unit 1 on the front of 407 North Allen. Both Units 1 and 2 have bay windows. See Attachments 1-1 and 1-2, which are recent photographs of 407 North Allen that show the bay windows. The bay windows on Unit 1 and Unit 2 are different - there are casement windows on Unit 2's bay windows and double hung windows on Unit 's. I believe the former owner of Unit 2 replaced the bay windows 5 to 10 years ago. The bay windows on Unit 1 are not original. They were probably installed in the 1950's.

We want to replace the three double hung bay windows of Unit 1 with wooden casement windows that match the bay windows on the second floor. The replacement windows will be wooden casement windows with simulated divided lights - SDL- made by Jeld - Wen. See Attachments 2-1, 2-2 and 2-3. The original window framing will remain in place and outside colors will not be changed.


The windows being replaced are drafty and leak. We have rotted wood and damaged plaster inside our condo unit underneath the windows. See Attachments 3-1, 3-2, 3-3 and 3-4.

Our goal is to fix the draft and water problem in a way that restores 407 to what we think was the architect's intended design. Matching our new windows with those on the second floor seems the way to go. This matching would be more in line with the architect's intended front elevation.


Attachments 4-1, 4-2, 4-3 and 4-4 are, we believe, Bascom Rowlett's 1924 elevation plans for 407 North Allen. They indicate casement bay windows on the first and second floor. They also suggest that Rowlett may have intended transom windows above the bay windows. We will not install transoms windows. We will match the casement windows without transom windows that CAR apparently approved for the second floor some years ago.

Attachment 5 is a photograph of 407 North Allen that, I believe, was taken in the 1960's. Assuming Rowlett built 407 North Allen per his plans, the casement windows of Unit 1 appear to have been replaced with double hung windows.


The contractor, Richard Colvin has worked on other homes on North Allen and the Fan.



407 WORTH ALLEN AVE ATTACKMENT 1-1




407 NORTH ALLEN AVE ATTACK MENT 1-2




CENTER UNIT-FIXED I REQUIRED

AHACHMONIT 2-1



SIDE UNIT FIXED Z REQUIRED

AHAMMENT 2-2



SIDE UNIT FIXED Z REQUIRED.




AHACHMENT 3-1





3-2





BASCOM ROWlett'S 1924 FRONT CLEUATIONS







AttACKMENT 1960'S Photo