

## COMMISSION OF ARCHITECTURAL REVIEW APPLICATION/CERTIFICATE OF APPROPRIATENESS

PROPERTY (Location of Work)	23223
319 N. 2754.	Richmond Ver 23029 unde Vill
Address // Y O F	1.1/1
Historic District / YOV/N CW	mai my
PROPOSED ACTION	
☐ Alteration (including paint colors)	☐ Rehabilitation ☐ Demolition
☐ Addition	☐ New Construction (Conceptual Review required)
Replacement	☐ Conceptual Review ☐ Final Review
OWNER 0 1-00	, APPLICANT (if other than owner)
Name Kaven Chase Tedle	Mocconame
Company	Company
Mailing Address 3/9 M. 27th 9	Mailing Address
RVA 33843	
Phone 804-877-0271	Phone Phone
Elliali	Signature Email
Signature 7/2///7	Date
Date // 7//	Date
ACKNOWLEDGEMENT OF RESPON	SIBILITY
provide a complete and accurate description	ludes all applicable information requested on checklists to of existing and proposed conditions. Preliminary review ry to process the application. Owner contact information and ications will not be considered.
	it is the responsibility of the applicant to determine if zoning should be prepared in compliance with zoning.
require staff review and may require a new ap	with all conditions of the COA. Revisions to approved work plication and CAR approval. Failure to comply with the COA he COA is valid for one (1) year and may be extended for an
(Space below for staff use only)	
Application received:	
Date/Time \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Complete
By ECE VED	COA - 021085 - 2017 Created 7/2016
JUL 27 2017	CUM - Created 7/2016

July 20, 2017

To: Commission Of Architectural Review

Re: Standard Porch replacement

This is a request for a review of attached plans. The existing porch is no longer safe and need to be removed and replaced. There are attached pictures showing deterioration and rot in all elements. The upper porch is no longer safe to use as the floor is sagging and rotted. I have also attached the form from the City of Richmond Permits and Inspection office to detail my specifications and dimensions of materials for the replacement.

The included photos will show both the current state of the existing porch and it can be seen that at some point there was an outside staircase whether it was original or not it would be hard to know. The current porch is clearly not original and is composed of more modern and inferior materials than would have been used in any original construction of this period.

The replacement will be constructed of treated lumber of the dimensions indicated on the porch section form. My interpretation of the regulations set forth in your material, Part III, Sec. 2, is that this project meets the criteria for an "in-kind replacement " of an existing porch.

We look forward to hearing from you about this project.

Sincerely,

Ted Petrocci/Karen Chase 319 N. 27th St. RVA, 23223



OUR BACK OF HOUSE IS BACK HERE THE VIEW OF OUR PORCH FROM THE STREET (OR LACK THEREOF) - Over the chain link, coiled wire, and left of all the 2015 installed, unapproved coooking vents on the restaurant.



**FULL EXTERIOR SHOTS** 







WOOD ROT AND CRUMBLING FLOOR, RAILINGS AND POSTS









= 1 FOOT

FUTURE/ NEW PLANS (ISH)

