

COMMISSION OF ARCHITECTURAL REVIEW APPLICATION / CERTIFICATE OF APPROPRIATENESS

PROPERTY (Location of Work))	1 6
Address 2235 MONUMENT AVENUE KILLY COVER CONDU					
Historic District City HISTORIC DISTRICT					
PROPOSED ACTION					
✓ Alteration (including paint colors)	☐ Reha	habilitation			emolition
☐ Addition	☐ New	ew Construction (Conceptual Review			quired)
		Conceptual F	Review	☐ Final Rev	view
OWNER Name PLKEY COUNT ASSOCIA Company PLKEY COURT ASSOCIA Mailing Address 2235 Monument VINIT 3 FULL MONTH NA 237 Phone 804 940 4183 Email atex wotringe grant. Signature Mullip Date 9/27/17	tave N 220 U	Company Address Mailing Address With 3 Phone 80	ex wo tesocial tesoci	hon provided in the second of	resident invent Ave (A 23220 Lailison
ACKNOWLEDGEMENT OF RESPONSIBILITY					
Requirements: A complete application includes all applicable information requested on checklists to provide a complete and accurate description of existing and proposed conditions. Preliminary review meeting or site visit with staff may be necessary to process the application. Owner contact information and signature is required. Late or incomplete applications will not be considered.					
Zoning Requirements: Prior to CAR review, it is the responsibility of the applicant to determine if zoning approval is required and application materials should be prepared in compliance with zoning.					
Compliance: If granted, you agree to complete require staff review and may require a new agree may result in project delays or legal action. Tadditional year, upon written request.	pplication and	d CAR appro	oval. Failur	e to comply v	vith the COA
(Space below for staff use only)					
Application received: ECE V	ED				
Date/Time SEP 2 8	2011	Complete [□ Yes	□ No	
COA-024475-2017 10:36	am				Created 7/2016

PROPOSAL

Location and Description:

The tiled lower landing front access first step off of the public sidewalk in front of 2235 Monument Avenue known as Rixey Court Condominium.

Due to age and wear, the tile inset is cracked, broken and raised because of an unstable base. There is no discernible concrete slab substructure. In it's present condition, the step creates a hazard of possible tripping or falling upon entry. The granite surround is in need of some repair.

Repair v. Replace:


Due to the instability of the area, all current tile and the substructure must be removed of all debris until solid ground is reached. Reconstruction will include the use of crushed stone for a solid base covered by a 4" slab for rebar.

Research has shown, the existing tile cannot be duplicated in configuration, style and color. Four stone masons were consulted and personally inspected the site. None could guarantee matching the pattern, shape or color of the existing tile and all agreed it would be too cost prohibitive to replicate even if a substitute could be found.

Proposal:

Further investigation of the neighborhood, revealed a number of properties fronting on Monument Ave. with a solid stone and similar granite surround entry. We propose to replace our entry step with a solid 6" limestone cut in three pieces to preserve the existing symmetry in the steps above. See attached drawing. In addition to mirroring the entries of numerous Historical Properties fronting on Monument Avenue, it would also be structurally sound and appealing visually as the combination of the limestone with the granite surround is compatible to the existing facade.

Current Condition





6" Limestone Slab



Existing Stair and Rail And Proposed Placement of Limestone



