

COMMISSION OF ARCHITECTURAL REVIEW

APPLICATION FOR CERTIFICATE OF APPROPRIATENESS

Address Address Historic district	ution of work) 13 M Street Union Hill		Date/time rec'd: Rec'd by: Application #: Hearing date:
APPLICANT INF	4 1		
Name / 1602	Aderson		Phone 434-407-3436
Company	N//t		Email Mandersonesquire egnail
Mailing Address	FILS M Street Richmons, VA 23223		Applicant Type: ✓ Owner □ Agent □ Lessee □ Architect □ Contractor □ Other (please specify):
OWNER INFOR	MATION (if different from ab	ove)	
Name			Company
Mailing Address		Y	Phone
			<u>Email</u>
PROJECT INFOR	RMATION		
Review Type:	☐ Conceptual Review	☐ Final Review	
Project Type:	Alteration	☐ Demolition	☐ New Construction
Project Description	n: (attach additional sheets if n		(Conceptual Review Required)
ACKNOWLEDGI	EMENT OF RESPONSIBILIT	Υ	
and may require a n		Failure to comply w	A. Revisions to approved work require staff review ith the COA may result in project delays or legal ional year, upon written request.
and accurate descrip additions, should me	otion of existing and proposed con	ditions. <u>Applicants p</u> ation and requireme	requested on checklists to provide a complete proposing major new construction, including ents prior to submitting an application. Owner ions will not be considered.
	ts: Prior to Commission review, it is it is the street it is not the street it is the street in the street is the street in the street is the street in the street in the street is the street in the street is the street in the street in the street is the street in the		of the applicant to determine if zoning approval is zoning.
Signature of Own	er		Date 2/10/14

2113 M Street


2113 M Street, also known as the William J. Clarke house, is a two-story, three-bay Greek Revival frame dwelling with a raised brick foundation, constructed c. 1856. The house has been vacant for approximately 10 years, and before that, was occupied by the same lady since the 1950s.


The original structure of the house is remarkably intact. "Improvements" in the 1950s and 1960s—such as insulated siding, linoleum floors, paneled walls and drop ceilings—had the effect of preserving the structure underneath.


The plans for the exterior consist replacing the lost front porch. The front porch was lost in a storm. Based on historical photos and the porch at 2115 M Street (originally constructed around the same time), we intend to build a two-story porch with a metal roof. The porch will be consistent with those on other vernacular Greek Revival houses in Union Hill. I still have the original 6X6 heart pine columns that supported the porch; these columns are identical to the original columns found on 2115 M Street that still support 2115 M Street's porch. Like 2115 M Street, the second story of the porch will not be accessible from the street.


The Commission previously requested installing the front porch stairs heading east, as in the 1940s picture. Since then it has been determined that those 1940s stairs were narrower and steeper than today's code permits. To install stairs 36 inches wide from the front porch 36-inch square landings are required at the top and bottom of the stairs. To accomplish this the original front facing stairs entering 2113 M Street would have to be removed hindering sidewalk access to the house. Additionally, the load bearing support beams closest to the sidewalk would have to be constructed on the retaining wall inches from the sidewalk. Moreover, a guard rail would also need to be installed on the retaining wall between the stairs the sidewalk further altering the front façade's appearance. I have included in this application pictures detailing the stair's dimensions demonstrating where the stair stringers would have to be located to meet modern code and run eastward.

The porch will be constructed from wood. The front porch will have 6X6 posts. It will be built to match the porch on 2115 M Street and have similar railings. It will utilize 4X6 salt treated beams for the framing similar to original construction. It will feature reclaimed tongue-and-grove heart pine for the decking. Roofing on the front porch will utilize standing seam metal, similar to what previously existed on the house.











1940's Photo From Watertines Museum Picture Detailing Original Cox6 Posts and Westward Stairs

Piture Detailing Where Front Stower Would Have To Be Located To Meet Modern Code



Modern Code Star Stringer Location





Westward Stairs

