



City of Richmond

City Hall
900 East Broad Street

Agenda

Commission of Architectural Review

Tuesday, June 28, 2016

3:30 PM

5th Floor Conference Room of City Hall

1 Call to Order

2 Roll Call

3 Approval of Minutes

April 26, 2016

May 24, 2016

4 Other Business

Secretary's Report

Administrative Approvals

Enforcement Report

Other Committee Reports

CONSENT AGENDA

- 1 [CAR No. 2016-091](#) 604 N. 22nd Street - Replace five windows on the front facade

Attachments: [Application & Plans](#)
[Site Map](#)
[Staff Report](#)

- 2 [CAR No. 2016-093](#) 614 N. 27th Street - Install a rear yard privacy fence and a balcony and 15 lite door on the second floor of the rear facade

Attachments: [Application & Plans](#)
[Site Map](#)
[Staff Report](#)

- 3 [CAR No.
2016-094](#) 2324 Monument Avenue - Replace in-kind an existing brick wall to include a vehicular gate
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)
- 4 [CAR No.
2016-095](#) 818 N. 25th Street - Replace deteriorated siding with smooth, unbeaded, fiber cement siding
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)
- 5 [CAR No.
2016-096](#) 2800-2802 E. Franklin Street - In-kind repair and rehabilitation of the front porch and replacement of brick stairs with wooden stairs
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)

REGULAR AGENDA

- 6 [CAR No.
2016-090](#) 3012 Monument Avenue - Install rooftop cellular antennas in a faux chimney structure
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)
- 7 [CAR No.
2016-092](#) 800 N. 22nd Street - Rehabilitate an existing home to include new fiber cement siding, windows, railings, deck, and fence and enclose an existing first floor porch
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)
- 8 [CAR No.
2016-099](#) 2312 Venable Street - Rehabilitate the structure to include installing fiber cement siding, repairing windows or installing new windows if necessary in existing openings, remove one 2nd floor door opening, and install two new doors
- Attachments:** [Application & Plans](#)
 [Site Map](#)
 [Staff Report](#)

