

Staff Report City of Richmond, Virginia

Commission of Architectural Review



1.COA-150679-2024	Final Review Meeting Date: 7/23/2024
Applicant/Petitioner	Alexandra Hamp
Project Description	Alteration - New Awnings
Project Location	212 2810 2000 2858 700 • 1 2755 2756 • 2129 704 • 2718 2000 2858 700 • • • • • • • • • • • • • • • • • •
Address: 2709 Monument Avenue	
Historic District: Boulevard, Monument Avenue	
High-Level Details:	
Applicant proposed to add two small awnings to the outside doors that lead into the back Chapel hall and from the Courtyard playground.	Boulevard 2795 2700 Avenue 255 256 256 257 200 200 200 200 200 200 200 20
Awning #1 Specs: 7-11 wide x 2-0 drop x 5-0 projection with 0-6 valance. Material to be Firesist and color to be Black.	
Awning #2 Specs: 6-0 wide x 3-0 drop x 5-4 projection with 0-6 rigid valence. Material to be Firesist and color to be Black.	200 511 015 200 013 000 512 000 013 000 513 010 015 00 514 015 00 013 000 515 00 00 00 00 00 515 00 00 00 00 515 00 00 00 00 515 00 00 00 515 00 00 00 515 00 00 00 515 0
Staff Recommendation	Approval, with Conditions
Staff Contact	Alex Dandrige, alex.dandridge@rva.gov, (804) 617 2496
Previous Reviews	None
Conditions for Approval	 The awning mounted hardware to be installed directly into the mortar joints to avoid damage to the historic masonry Applicant to work with staff for final placement, design, and materials

Staff Analysis

Guideline Reference	Reference Text	Analysis
Building Elements, Awning Design & Placement p. 72	 Awnings should be placed carefully so that building elements or existing materials are not damaged or obscured. Awning mounting hardware should be installed directly into mortar joints to avoid damage to historic masonry. 	The applicant proposes to install two new awnings. Staff finds that the proposed awnings are in keeping with the <i>Guidelines</i> and recommends approval with the condition that <u>the awnings be anchored into the mortar, not the</u> <u>historic brick</u> .

Building Elements, Awning Fabric & Color p. 72	 6. The choice of colors should be coordinated as part of an overall color scheme, and solid colors, wide stripes and narrow stripes may be considered inappropriate, depending on existing on-site conditions. 7. There is a wide variety of materials ranging from traditional painted cotton to new acrylic fabrics. Most awnings can be washed. 	The applicant's application & plans with the corresponding preliminary renderings are generally satisfactory and is in keeping with the neighborhood's historic character and design. Staff finds that the proposed awnings are in keeping with the <i>Guidelines</i> and recommends approval with the condition that <u>the Applicant work with staff for final placement, design, and materials.</u>
---------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

It is the assessment of staff that, with the conditions above, the application is consistent with the Standards for Rehabilitation and New Construction outlined in Section 30-930.7 (b) and (c) of the City Code, as well as with the Richmond Old and Historic Districts Handbook and Design Review Guidelines, specifically the pages cited above, adopted by the Commission for review of Certificates of Appropriateness under the same section of the code.

Figures

Figure 1. Door from playground off Monument Ave.



Figure 2. Door to chapel on ramp side of Bell Tower on Monument Ave.

