

Commission for Architectural Review Application for Certificate of Appropriateness

900 E. Broad Street, Room 510 Richmond, VA 23219 | (804)-646-7550





Property (location of work)

3203 Monument Ave. Richmond, VA 23221

Address:			
Historic District: Monument Ave.			
Applicant Information	Owner Information Billing Contact Same as Applicant		
Email: wdavies@vamasonryrestoration.com	Name: Samuel W. Daniel Email: SWD@danielco.net		
Phone: 804-519-5171			
Company: Virginia Masonry Restoration	Phone: 804-840-1544 Company: n/a		
Mailing Address: P.O. Box 6749			
1800 Roseneath Rd., Richmond, VA 23230	Mailing Address:		
Applicant Type: Owner Agent Lessee	3203 Monument Ave. Richmond, VA 23221		
☐Architect ✔Contractor ☐Other (specify):			
	Owner must sign at the bottom of this page		
Project Information			
Project Type: Alteration Demolition	☐New Construction (Conceptual Review Required)		
Description (attach additional sheets if needed):			
Rebuilding failed front entrance masonry- See attack	ched narrative, renderings, and architectural drawings.		
Acknowledgement of Responsibility			

Compliance: If granted, you agree to comply with all conditions of the certificate of appropriateness (COA). Revisions to approved work require staff review and may require a new application and approval from the Commission of Architectural Review (CAR). Failure to comply with the conditions of the COA may result in project delays or legal action. The COA is valid for one (1) year and may be extended for an additional year, upon written request and payment of associated fee.

Requirements: A complete application includes all applicable information requested on checklists available on the CAR website to provide a complete and accurate description of existing and proposed conditions, as well as payments of the application fee. <u>Applications proposing major new construction, including additions, should meet with staff to review the application and requirements prior to submitting an application.</u> Owner contact information and signature is required. Late or incomplete applications will not be considered.

Zoning Requirements: Prior to Commission review, it is the <u>responsibility of the applicant</u> to determine if zoning approval is required and application materials should be prepared in compliance with zoning.

Signature of Owner	Januell.	Vanuel	Date <u>25 Feb 22</u>
--------------------	----------	--------	-----------------------



CERTIFICATE OF APPROPRIATENESS

ALTERATION AND ADDITION CHECKLIST

<u>Well in advance</u> of the COA application deadline contact staff to discuss your project, and if necessary, to make an appointment to meet with staff for a project consultation.

Complete all applicable sections and submit with the COA application form. Staff can assist you in determining what items are required for your scope of work. An incomplete application may cause delays in processing or may be deferred to the next agenda. Application materials <u>must</u> clearly represent current and proposed conditions. Refer to Standards for Rehabilitation outlined in Section 30.930.7(b) of the City Code, as well as, the *Richmond Old and Historic Districts Handbook and Design Review Guidelines*.

PROPERTY ADDRESS:					
BUILDING TYPE		ALTERATION TYPE			
single-family residence	☐ garage	☐ addition	□ roof		
☐ multi-family residence	✓ accessory structure	☐ foundation	☐ awning or canopy		
☐ commercial building	□ other	☐ wall siding or cladding	☐ commercial sign		
☐ mixed use building		\square windows or doors	☐ ramp or lift		
☐ institutional building		porch or balcony	□ other		
WRITTEN DESCRIPTION					
property description, current conditions and any prior alterations or additions					
proposed work: plans to change any exterior features, and/or addition description					
current building material conditions and originality of any materials proposed to be repaired or replaced					
proposed new material description: attach specification sheets if necessary					
PHOTOGRAPHS place on 8 ½ x 11 page, label photos with description and location (refer to photograph guidelines)					
☐ elevations of all sides					
☐ detail photos of exterior elements subject to proposed work					
☐ historical photos as evidence for restoration work					
DRAWINGS (refer to require	d drawing quidelines)				
current site plan	☐ list of current windows an	d doors	vations (all sides)		
proposed site plan	☐ list of proposed window a		elevations (all sides)		
☐ current floor plans	☐ current roof plan	☐ demolition			
☐ proposed floor plans	☐ proposed roof plan	☐ perspective	e and/or line of sight		
☐ legal "plat of survey"			_		



Masonry Assessment

February 24, 2022

Virginia Masonry Restoration P.O. Box 6749 1800 Roseneath Rd. Richmond, VA 23230

Contractor License #: 2705155443 Class A

Attn: Alex Dandridge, Secretary

Commission of Architectural Review

Project: 3203 Monument Ave.

Richmond, VA 23221

Monument Ave. Old and Historic District

Owner: Samuel W. Daniel

Subject: Assessment of Existing Structure and Recommendations for Rehabilitation

Prepared by: Warren Davies

Introduction

3203 Monument Ave. is a Georgian Revival style house built in 1910 with a front entrance that is elevated approx. 5' above the city sidewalk. This application is for design approval to replace the failed masonry structures that combine to contain the elevated landscape elements and provide access to the porch and main entrance to the house, specifically:

- 1. (2) Brick retaining walls adjacent to the city sidewalk.
- 2. Concrete steps between the city sidewalk and the porch.
- 3. Concrete porch deck.

These elements are not original to the house and are in fact inconsistent with the building style. Our intent is to remove these structures and replace them with material and design that is more appropriate to a Georgian Revival style house while maintaining their current footprint.

Existing Conditions

Brick Retaining Walls

The existing brick retaining walls appear to have been built during the 1950s or 1960s. The brick are typical of brick of that time period and the mortar joints were tooled with a round jointer which was not used anywhere else on the house.

The walls have been painted white by previous owners. The paint has peeled regularly over the years which has created a maintenance problem and the paint is not allowing the masonry to breathe so the mortar between the layers of brick has started to deteriorate at an accelerating rate.

The walls have structural cracks caused by the hydrostatic pressure of water saturated within the retained soil. At some point attempts were made to salvage the wall with tension bars anchored into the yard behind the wall but the structure has continued to crack and is in fact leaning out into the city sidewalk.

Concrete Steps

The concrete steps have significant structural cracks, but the larger objection is to the inconsistency of the tread depths and the riser heights. Some riser heights are close to 9" while others are closer to 6". These steps are dangerous and do not meet code. The steps appear to have been rehabilitated in the past by adding thin layers of cement to hide the failed concrete below.

Concrete Porch Deck

The porch deck is not original. The concrete has a large structural crack in the middle, and it has settled to create a "bowl" where water collects during driving rains. The porch has been patched in the past with concrete leveling cement, but the patching was poorly executed and doomed to fail due to the movement of the slab below.

Determination of Scope

The project was originally intended to be performed in phases and started with a primary focus on the retaining walls because they are failing and so incongruent with the rest of the house, however, during the planning it became clear that it would be very difficult to rehabilitate the porch and steps once the new walls were built. It was also determined that leaving some inappropriate style elements in place might complicate the review process because it would be difficult to present a cohesive design.

Design Materials

The design relies on the use of brick and granite. The brick will be unpainted handmade wood molds that match the common brick on the house and chimneys. The mortar will be a traditional lime mortar and the joints will also match the joints on the house and chimneys in both color and profile.

The granite is a light gray granite that matches granite walls and entrances throughout Monument Ave. and the Fan District.

Brick and Granite Wall Design

The walls will be much lower than the existing walls so that they are less prominent. The yard grade will be adjusted to meet the height of the lower walls. The new walls will sit on new concrete footings as shown in the attached drawings and the back side of the wall will have a gravel drain field to control water that is carried from the yard. This drain field, combined with the lowering of the wall will prevent the wall from being pushed over by hydrostatic pressure in the future.

There are some small columns at the ends of each wall. These provide an ornate element common to Georgian Revival style, but they also serve to create more elegant transitions from the side walls to the front walls where higher retaining walls are needed adjacent to the existing steps. (See attached rendering SK-3).

The granite capstones are 4" thick material intended to tie into the quoins on the house façade and to maintain the style of many other entrances on homes along Monument Ave.

The walls on either side of the new steps will have a minimal projection above grade as needed to encapsulate the step treads.

Front Porch Design

The brick walls supporting the existing porch concrete will remain in place with minor repairs as needed using lime mortar. The paint will be removed from the brick walls to expose the original brick surface. The intent is to tie the design of the new retaining walls into the original porch design. The new brick will be the same color as the existing porch brick.

The existing porch has a concrete "coping stone" appearance. The new porch will maintain that appearance with large units of granite coping. The new porch concrete will be covered with granite paving.

Summary

The new structures will be built in the exact footprint of the existing elements with a design style more appropriate to the period and consistent with the material and design of many other houses on Monument Ave.

Thank you,

Warren Davies Virginia Masonry Restoration



Structural Cracks at Front Retaining Wall- Right Side



Structural Cracks and Separation of Masonry at Front Retaining Wall- Left Side



Concrete Steps Showing Previous Repair Attempts



Concrete Steps Showing Inconsistent Treads/Risers and Structural Cracks



Retaining Wall Leaning into City Sidewalk




Top of Porch Showing Structural Cracks and Sunken "Bowl"


SAMUEL W. DANIEL RESIDENCE

FRONT ENTRANCE STEPS AND RETAINING WALL

3203 MONUMENT AVE. RICHMOND, VIRGINIA 23221







1800 ROSENEATH RD.
RICHMOND, VA 23230
P: 804-519-5171
WWW.VAMASONRYRESTORATION COM-

RONT ENTRANCE STEPS AND RETAINING WALL

DATE

24 FEBRUARY 2022

DRAWING TITLE:

COVER SHEET

CS





1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.COM

FRONT ENTRANCE STEPS AND RETAINING WALL


DATE

24 FEBRUARY 2022

DRAWING TITLE:

VIEW FROM CENTER LOOKING SOUTH

SK-1





1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.COM

FRONT ENTRANCE STEPS AND RETAINING WALL


DATE:

24 FEBRUARY 2022

DRAWING TITLE:

VIEW FROM LEFT ANGLE LOOKING SOUTH WEST

SK-2





1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.CO

FRONT ENTRANCE STEPS AND RETAINING WALL


DATE:

24 FEBRUARY 2022

DRAWING TITLE:

VIEW FROM RIGHT ANGLE LOOKING SOUTH EAST

SK-3



SITE PLAN







1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.COM

FRONT ENTRANCE STEPS AND RETAINING WALL


DATE:

24 FEBRUARY 2022

DRAWING TITLE:

SITE PLAN

A1.0



NORTH ELEVATION

Virginia Masonry



1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.COM

FRONT ENTRANCE STEPS AND RETAINING WALL


DATE:

24 FEBRUARY 2022

DRAWING TITLE:

NORTH ELEVATION

A2.0





1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171


WWW.VAMASONRYRESTORATION.COM


STEPS AND

24 FEBRUARY 2022

WEST **ELEVATION**

A2.1





WALL SECTION

3. BACKFILL WALL WITH #57 GRAVEL, AND DRAIN TILE WRAPPED IN FILTER CLOTH.

Virginia Masonry



1800 ROSENEATH RD. RICHMOND, VA 23230 P: 804-519-5171

WWW.VAMASONRYRESTORATION.COM

FRONT ENTRANCE STEPS AND RETAINING WALL

DATE:

24 FEBRUARY 2022

DRAWING TITLE:

WALL SECTION

A3.1

