

COA-027102-2017

COMMISSION OF ARCHITECTURAL REVIEW APPLICATION / CERTIFICATE OF APPROPRIATENESS

PROPERTY (Location of Work)			
Address 730 North 23 Rd		34.	
Historic District UNION HILL			
PROPOSED ACTION			
☑ Alteration (including paint colors)		Rehabilitation	□ Demolition
☐ Addition		New Construction (Conce	ptual Review required)
		☐ Conceptual Review	☐ Final Review
OWNER		APPLICANT (i	f other than owner)
Name Kosalind Jackson		Name Charstop	BER TURNER
Company			2 Streat GROUPLLC
Mailing Address 730 North 23rd 3	<u> </u>		23 Cookes FARM DR
Phone 804-837-7904		Kighmond, WI	· · · · · · · · · · · · · · · · · · ·
Phone 804-837-7904 Email 10257@MssJ.com			7-3707
Signature Resolut Jackim		Email TURNERSH Signature	REATCROUP@ CMAPL.Co.
Date ///22/17		Date	
		54,0	
ACKNOWLEDGEMENT OF RESPONS	IBIL	ITY	
Requirements: A complete application include provide a complete and accurate description of meeting or site visit with staff may be necessary signature is required. Late or incomplete applications.	of ex to pr	isting and proposed con- ocess the application. Ov	ditions, Preliminary review
Zoning Requirements: Prior to CAR review, it approval is required and application materials shaped and application materials.	is the rould	e responsibility of the appli be prepared in complianc	icant to determine if zoning e with zoning.
Compliance: If granted, you agree to comply we require staff review and may require a new appliance may result in project delays or legal action. The additional year, upon written request.	icatio COA	n and CAR approval. Fai	lure to comply with the COA
(Space below for staff use only)			
Application received: NOV 2 2	201	7	
Date/Time		Complete	□ No
Ву			
0-10 0001-0-0			Created 7/2016



CERTIFICATE OF APPROPRIATENESS

ALTERATION AND ADDITION CHECKLIST

<u>Well in advance</u> of the COA application deadline contact staff to discuss your project, and if necessary, to make an appointment to meet with staff for a project consultation.

Complete all applicable sections and submit with the COA application form. Staff can assist you in determining what items are required for your scope of work. An incomplete application may cause delays in processing or may be deferred to the next agenda. Application materials <u>must</u> clearly represent current and proposed conditions. Refer to Standards for Rehabilitation outlined in Section 30.930.7(b) of the City Code, as well as, the *Richmond Old and Historic Districts Handbook and Design Review Guidelines*.

PF	ROPERTY ADDRESS: _	7	30 North 23rd	SH						
В	JILDING TYPE			AL	TERATIO	N T	YPE			
囡	single-family residence		garage		addition				roof	
	multi-family residence		accessory structure		foundation				awning or canopy	
	commercial building		other	Ø	wall siding	or cl	adding [commercial sign	
	mixed use building			×	windows or	doc	ors [ramp or lift	
	institutional building				porch or ba	lcon	y E		other	
WI	RITTEN DESCRIPTION									
	property description, curren	t cor	nditions and any prior altera	ition	s or addition	ıs				
	_									
3 P										
印										
PH	IOTOGRAPHS place on 8	3 ½ :	x 11 page, label photos with	n de	scription and	d loc	ation (refer to	nh	otograph quidelines)	
	elevations of all sides		, . 3 - ,					р	ologiapii galdomioa,	
Q										
DR	AWINGS (refer to required	d dra	awing guidelines)							
	current site plan		list of current windows and	d do	ors		current elevat	tior	ns (all sides)	
	proposed site plan		list of proposed window ar	id de	oor		proposed elev	vat	ions (all sides)	
	current floor plans		current roof plan				demolition pla	an		
	proposed floor plans		proposed roof plan				perspective a	nd	or line of sight	
	legal "plat of survey"									




Turner Streat Group LLC 6423 Cookes Farm Drive Richmond VA 23231

Invoice No.

804-337-3707 fax 804-795-1778

Name Ms Jackson Address City 730 N 23rd St City Phone Qty Description Scrape loose paint from building exterior Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Address City Phone State VA ZIP Description Order No. Rep FOB TOTAL Scrape loose paint from building exterior Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
City Phone Description City Description Corract damaged morter joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Qty Description Unit Price TOTAL Scrape loose paint from building exterior Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Scrape loose paint from building exterior Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Scrape loose paint from building exterior Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Remove loose morter in joints Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Correct damaged morter joints Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Prime exterior brick surfaces with two coats of kilz 2 Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Paint exterior with two coats of Valspar exterior paint Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Reattach loose bricks Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Remove vinyl siding and trim Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Inspect exetior surfaces for damage Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis]
Install vapor barrior over surfaces Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Install Hardie Board in place of vinyl siding Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Prime and paint siding two coats each Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Remove vinyl windows and exterior trim Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Install new wood clad double hung windows Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Install exterior trim around new windows Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Install trim around interior of new windows Relocate rear door to window opening Remove all job related derbis	
Relocate rear door to window opening Remove all job related derbis	
Remove all job related derbis	
SubTotal \$0.0	00
Payment Details Shipping & Handling	-
Cash Taxes	-
• Check	
Credit Card TOTAL \$0.0	00
Name CC#	
I Uffice Use Only	
Expires	
Account in publicular 51	
Account is subject to a Finance Charge for late payment, computed at an Annual	
Percentage Rate of 18% on total past due balance plus Attorney Fees!	
Current Crnt-30 Crnt-60 Crnt-90	





COMMISSION OF ARCHITECTURAL REVIEW

WINDOW ASSESSMENT FORM

-
0
Q
(D)
3
7
~
Þ
_
ш.
3
nó.
ĹĎ
ĹĎ.
-:




COMMISSION OF ARCHITECTURAL REVIEW


WINDOW ASSESSMENT FORM


Property Address: 430 North 23Rd ST

					ų		
7	4	W	13		J-7	Window#	
Double	Double Hung	Huma	Double	Double	Double- hung 2/2	Style	Window Information
24 × 24%	光文学	£×8	花×床	Zׯ	36" × 78"	Width and Height	nformati
1505	VINVI	NEWLI	lyndy	NAT Y	Wood	Material	9
					Poor	Paint condition?	Ger
YES	Y65	玄	**	K.	Yes	Square?	General Condition
YES YES NO	YES NO	Yes	455	¥55	No	Operable?	onditi
70	No	20	No	2	Yes	Missing or broken panes?	웈
					2	Sill and Head	
					Н	Jambs	
					2	Rails	Window Assessmen
					1	Stiles	ow Ass
					н	Muntins	iessm
					ω	Panes and Glazing Putty	int
					10	Total Value	
				Replace VINY (windows	Replace and reglaze broken panes, waterproof and repaint wood.	Proposed treatment	



730 NORTH 23 RD ST





730 NORTH 23 RD ST