

## **COMMISSION OF ARCHITECTURAL REVIEW**

APPLICATION FOR CERTIFICATE OF APPROPRIATE IN ENTERING IN ENTERING

PROPERTY (location of work)			Date/time rec'd: JUN 2 8 2019		
Address 3017 E.Marshall St. , Richmond VA ,23223			Rec'd by:		
Historic district St John's Church			Application #: Hearing date:		
APPLICANT INFORMATION			(UA-057055-2019		
Name Sarah Meriem Benslimane			Phone (504) 930-0405		
Company		Email smbensli@gmail.com			
Mailing Address 3017 E.Marshall St. , Richmond VA ,23223			Applicant Type: ☑ Owner ☐ Agent☐ Lessee ☐ Architect ☐ Contractor☐ Other (please specify):		
OWNER INFORI	MATION (if different from ab	oove)			
Name			Company		
Mailing Address			Phone		
			Email		
PROJECT INFOR	MATION				
Review Type:	☑ Conceptual Review	Final Review			
Project Type:	□ Alteration	☑ Demolition	☐ New Construction		
Project Description	: (attach additional sheets if r	needed)	(Conceptual Review Required)		
Please see str	uctural engineer's report about sc	ope of project. Thank	you.		

### **ACKNOWLEDGEMENT OF RESPONSIBILITY**

Compliance: If granted, you agree to comply with all conditions of the COA. Revisions to approved work require staff review and may require a new application and CAR approval. Failure to comply with the COA may result in project delays or legal action. The COA is valid for one (1) year and may be extended for an additional year, upon written request.

Requirements: A complete application includes all applicable information requested on checklists to provide a complete and accurate description of existing and proposed conditions. Applicants proposing major new construction, including additions, should meet with Staff to review the application and requirements prior to submitting an application. Owner contact information and signature is required. Late or incomplete applications will not be considered.

**Zoning Requirements:** Prior to Commission review, it is the responsibility of the applicant to determine if zoning approval is required and application materials should be prepared in compliance with zoning.

Signature of Owner	Sarah M. Be	enslimane	Date	06/27/2019	

305 N Allen Avenue Richmond Virginia 23220 telephone 804 353 3130

KONEFAL & COMPANY, INC

email skonefal@gmail.com www.konefal.company

June 27, 2019

RE: 3017 New Porch

#### **Existing Porch Condition:**

The existing house structure and porch exhibit signs of significant deterioration and the porch is currently in a state of partial collapse, being held in place with temporary bracing. The front wall of the house is in need of reinforcement so that it may provide lateral stability to the structure. The extent of the reinforcement will be evaluated at the time of demolition, when the front wall framing can be revealed.

#### **Existing Porch Style:**

It is believed by the owner that the existing front porch, queen anne style with a second floor balcony, is not original to the house. The owner would like to replace this style with a porch that is consistent with other wood-framed houses in the street.


#### **Proposed Work:**

The existing porch structure is deteriorated. The proposed work includes the demolition of the existing structure and construction of a new front porch, removing the upper level balcony access. A new window will be installed at the location of the second floor door. There will be work to repair and reinforce the front wall structure, but the scope of this work will be determined during the demolition phase.

#### **Proposed Materials:**

The new work is proposed to be a treated wood structure. The balustrade is proposed to be urethane millwork from HAAS Architectural Millwork and columns are proposed to be fiberglass 'PERMAcast' from HB&G. The roof would be a low-seam metal roof with half-round gutters. The flooring would be composite tongue and groove.

The existing windows have a diagonal mullion pattern in the top sash. A single new window is proposed at the second floor to match this configuration.





The existing porch is in a state of partial collapse





Existing columns have punched through deteriorated framing at the ground floor



**EXISTING PORCH** Scale: 1/4" = 1'-0"



Deterioration is evident in the porch upper level and ground floor,

KONEFAL 4 COMPANY 44 305 N Allen Avenue

Richmond Virginia 23220 telephone 804 353 3130

email skonslat@gmail.com www.honefal.company

3017 E MARSHALL ST RICHMOND VA, RICHMOND, VA 23223 OWNER: SARAH BENSLIMANE FRONT PORCH RECONSTRUCTION

**PORCH EXISTING** CONDITION

JUNE 27, 2019


**D2** 


Deterioration of the front wall Deterioration of the front wall of the house is significant. Evaluation of the extent of damage is proposed during the demolition of the porch. Repair and reinforcement of the front wall framing is necessary for the structural integrity of the house


The extent of the repair will be determined when the framing revealed.

**EXISTING PORCH** 

**EXISTING PORCH** 







# DESCRIPTION

SIZE 21 × 90.

E Single family direlling

GINAL USE SINGLE FAMILY